

# Product Change Notification



## Change Notification # 2010100106A

### BIOS Update for PIP9-1E

Initial Release Date: 2010 October 8  
Last Revision Date: 2010 October 8  
Change Type: BIOS/Firmware Change  
Affected Product Family: PIP (Packaged Industrial PC)  
Reason for Change: BIOS Update to V2.00  
Anticipated impact on Form, Fit and Function: Minor impact anticipated  
Anticipated impact on Quality or Reliability: Improved Quality and Reliability anticipated  
Customer contact: [info@mpl.ch](mailto:info@mpl.ch)

### Detailed Description of Change

The affected products receive a new BIOS release (V2.00). See the 'BIOS Release Notes' section below for a detailed overview of the changes.

### Affected Products List

<b>Sales Part#</b>	<b>MPL Manufacturing Part#</b>	<b>MPL Component Stock#</b>	<b>Replacement Part#</b>
PIP9-1E	MED-10361-191 Rev. B and later	-	-
PIP9-1E	MED-10361-091 Rev. A and later	-	-

### PCN Revision History

<b>Revision</b>	<b>Date</b>	<b>Description</b>
A	2010-10-08	Initial Release

Title BIOS Update for PIP9-1E			Page 1 / 2	
Written	Date 08/10/10	Visa MW	PCN # <b>2010100106A</b>	Rev. A

# Product Change Notification



## BIOS Release Notes

**BIOS Version: 2.00**

**Information:**

- **Build date:** 09/30/10 (mm/dd/yy)
- **BIOS No:** MEV-10114-291
- **Core BIOS:** Phoenix® Embedded BIOS® w/StrongFrame® Technology, V6.005
- **VGA BIOS:** PC14.4 build 1270
- **PXE Boot ROM:** Intel® Boot Agent v1.3.53

**Features & Fixes:**

- Initial BIOS release, based on Phoenix® EBSF.005
- All-new Setup Menu System
- BBS (BIOS Boot Specification) supported
- Removed support for UPS-1

Title			BIOS Update for PIP9-1E		Page
					2 / 2
Written	Date	Visa	PCN #	Rev.	
	08/10/10	MW	<b>2010100106A</b>	<b>A</b>	