

Product Change Notification



Change Notification # 2010100109A

BIOS Update for PIP7-11

Initial Release Date: 2010 October 8
Last Revision Date: 2010 October 8
Change Type: BIOS/Firmware Change
Affected Product Family: PIP (Packaged Industrial PC)
Reason for Change: BIOS Update to V2.00
Anticipated impact on Form, Fit and Function: Minor impact anticipated
Anticipated impact on Quality or Reliability: Improved Quality and Reliability anticipated
Customer contact: info@mpl.ch

Detailed Description of Change

The affected products receive a new BIOS release (V2.00). See the 'BIOS Release Notes' section below for a detailed overview of the changes.

Affected Products List

<i>Sales Part#</i>	<i>MPL Manufacturing Part#</i>	<i>MPL Component Stock#</i>	<i>Replacement Part#</i>
PIP7-11	MED-10296-071 Rev. E and later	-	-

PCN Revision History

<i>Revision</i>	<i>Date</i>	<i>Description</i>
A	2010-10-08	Initial Release

Title BIOS Update for PIP7-11			Page 1 / 2	
Written	Date 08/10/10	Visa MW	PCN # 2010100109A	Rev. A

Product Change Notification



BIOS Release Notes

BIOS Version: 2.00

Information:

- **Build date:** 09/30/10 (mm/dd/yy)
- **BIOS No:** MEV-10100-271
- **Core BIOS:** Phoenix® Embedded BIOS® w/StrongFrame® Technology, V6.005
- **VGA BIOS:** PC14.4 build 1270
- **PXE Boot ROM:** Intel® Boot Agent v4.1.21

Features & Fixes:

- Initial BIOS release, based on Phoenix® EBSF.005
- All-new Setup Menu System
- BBS (BIOS Boot Specification) supported
- Removed support for UPS-1

Title			BIOS Update for PIP7-11		Page
					2 / 2
Written	Date	Visa	PCN #		Rev.
	08/10/10	MW	2010100109A		A