

Product Change Notification



Change Notification # 2014031301A

BIOS Update for PIP6-11

Initial Release Date: 2014 March 13
Last Revision Date: 2014 March 13
Change Type: BIOS/Firmware Change
Affected Product Family: PIP (Packaged Industrial PC)
Reason for Change: BIOS Update to V1.12
Anticipated impact on Form, Fit and Function: Minor impact anticipated
Anticipated impact on Quality or Reliability: Improved Quality and Reliability anticipated
Customer contact: info@mpl.ch

Detailed Description of Change

The affected products receive a new BIOS release (V1.12). See the 'BIOS Release Notes' section below for a detailed overview of the changes.

Affected Products List

<i>Sales Part#</i>	<i>MPL Manufacturing Part#</i>	<i>MPL Component Stock#</i>	<i>Replacement Part#</i>
PIP6-11	MED-10407-001 [A, B, C, D]	-	-

PCN Revision History

<i>Revision</i>	<i>Date</i>	<i>Description</i>
A	2014-03-13	Reflect BIOS V1.12

Title BIOS Update for PIP6-11			Page 1 / 2	
Written	Date 13/03/14	Visa MW	PCN # 2014031301A	Rev. A

Product Change Notification



BIOS Release Notes

BIOS Version: 1.12

Information:

- **Build date:** 03/12/14 (mm/dd/yy)
- **BIOS No:** MEV-10121-001
- **Core BIOS:** Phoenix® Embedded BIOS® w/StrongFrame® Technology, V6.907
- **VGA BIOS:** Intel® SCH Chipset VGA BIOS Build 0017
- **PXE Boot ROM:** Intel® Boot Agent GE v1.3.72

Features & Fixes:

- Improved detection of SSD drives

Title			BIOS Update for PIP6-11		Page
					2 / 2
Written	Date	Visa	PCN #	Rev.	
	13/03/14	MW	2014031301A	A	